

March 11, 2010

Tie-In Welding (Pipeline)

PURPOSE/APPLICATION:

Tie-in welding is a necessary procedure when building a Pipeline. Tie-in points are where two joints of pipe are welded together to complete a pipeline. Generally Tie-in's are completed in a ditch or Bell Hole. Tie-in welds may also occur above ground as well.

PPE

- Safety Glasses
- Face shield/welders mask
- Welding Gloves
- Fire Retardant Clothing
- Personal Gas Monitor

TRAINING

- Certifications
- Orientation
- Training

TOOLS/EQUIPMENT

- Side Boom/Crane
- Cutting Torch
- Grinders
- Line-Up Clamps
- Ladders
- Slings
- Pipeline Skids
- Pipe Beveller
- Tiger Torch
- Propane

| # | Job Steps | Hazards | Control Measures |
|---|--|--|--|
| 1 | Set pipe in ditch for tie-in weld using Side Boom or Crane | <ul style="list-style-type: none"> ▪ Suspended loads ▪ Mechanical Failure ▪ Sling Failure | <ul style="list-style-type: none"> ▪ Never work under a suspended load ▪ Equipment Inspections ▪ Use Tag Lines |
| 2 | Set pipe on Pipeline Skids or cones in ditch | <ul style="list-style-type: none"> ▪ Pinch Points ▪ Confined space ▪ Improper Rigging | <ul style="list-style-type: none"> ▪ Ensure Cones or skids are on level ground and sturdy ▪ Competent persons rigging pipe |



SAFE JOB PROCEDURE

SJP-29

March 11, 2010

Tie-In Welding (Pipeline)

| # | Job Steps | Hazards | Control Measures |
|---|--|--|---|
| 3 | Mark pipe and use beveller or torch to cut to size | <ul style="list-style-type: none">▪ Burns▪ Explosion/Fire Hazard▪ Explosive Atmosphere | <ul style="list-style-type: none">▪ Monitor Atmosphere at all times▪ Ensure Fire Extinguisher is present▪ Wear all required PPE at all times▪ Ensure pipe is supported by skids or mechanical means on each side of the tie-in point before cutting pipe |
| 4 | Pre-heat pipe as per requirements with Tiger Torch | <ul style="list-style-type: none">▪ Burns | <ul style="list-style-type: none">▪ Never place propane bottles in ditch▪ Use Temperature Sticks or a Heat Probe to determine required temperature |
| 5 | Attach Line-Up Clamps on pipe for alignment | <ul style="list-style-type: none">▪ Pinch points | <ul style="list-style-type: none">▪ Ensure right tools for the job▪ Never place hands in ends of pipe |
| 6 | Tack Weld joints together in preparation for completion weld | <ul style="list-style-type: none">▪ Arc flash▪ Spark spray▪ Stored Energy | <ul style="list-style-type: none">▪ Wear PPE▪ Restrict access to area to prevent congestion▪ Rotate Line-Up Clamps when necessary to achieve sufficient tack before removing clamps (50%) |
| 7 | Remove Line-Up Clamps and finish welding joint | <ul style="list-style-type: none">▪ Heavy lifting | <ul style="list-style-type: none">▪ Get help for lifting heavy objects▪ Use your legs not your back while lifting heavy objects |

Additional Precautions:

REFERENCE/REGULATIONS

- Alberta OH&S Code
 - Part 2 Hazard Assessment, Elimination And Control
 - Part 6 Cranes, Hoists And Lifting Devices
 - Part 10 Fire And Explosion Hazards
 - Part 14 Lifting And Handling Loads
 - Part 18 Personal Protective Equipment
 - Part 19 Powered Mobile Equipment
- Saskatchewan OH&S Regulations
 - Part 3 General Duties
 - Part 7 Personal Protective Equipment
 - Part 11 Powered Mobile Equipment
 - Part 13 Hoists, Cranes And Lifting devices
 - Part 14 Rigging
 - Part 25 Fire And Explosion Hazards
- British Columbia OH&S Regulations
 - Part 4 General Conditions
 - Part 8 Personal Protective Clothing And Equipment
 - Part 14 Cranes And Hoists
- Part 15 Rigging

Developed by: 1. Jay Pilon 2. _____ Date: March 11, 2010
3. _____ 4. _____

Revised by: 1. _____ 2. _____ Date: _____
